

BERNINA Firmware Release
B 710 / 780 V 35.13.17
B 750 QE V 35.13.18

Steckborn, 16.03.2016

Information on Firmware Update

The firmware for the BERNINA B 710 / 750 QE / 780 has been updated and optimized. In this release note only the most relevant changes are listed.

Note:

BERNINA recommends all their customers of the corresponding product class to always use the latest software (Firmware release) as we keep on improving it according to customer feedback and wishes, considering new features, general optimization as well as a removal of defects to ensure the best possible sewing and embroidering experience on the BERNINA Product.

Functional Improvements:

- **General – Missing welcoming text (B 710)**
During the start-up of the machine the welcoming text was missing. This fault has been removed.
- **Sewing/Embroidering - Message ‘Too much fabric under the presser foot’ (B 780)**
With some machines the thickness of the fabric couldn't be detected correctly by the sensor. As a result the message ‘Too much fabric under the presser foot’ appeared, although the fabric thickness under the presser foot was tolerable. This fault has been corrected and the message only appears when the allowed amount of fabric is exceeded.
- **Embroidering – Embroidery motif selection by number (B 750 QE)**
When selecting embroidery motifs by number entering, it could have happened that the software of the machine crashed. This fault has been removed.

BERNINA International AG endeavors to keep improving and optimizing their products basing on customer feedback and the latest technical developments.

Kind regards,

BERNINA International AG
Steckborn, Switzerland