BERNINA Firmware Release
BERNINA 530 and BERNINA 550 QE
V.20120319

Steckborn, 15th March 2012

The following issues of the latest Firmware concerning BERNINA 530 and BERNINA 550 have been optimized:

1.) As the minimum speed range was adjusted too hard, precise sewing with slightly pressed foot control was difficult. The sensitivity of the foot control has therefore been revised and optimized.
2.) The piercing support for thick and heavy material has been revised and optimized.
3.) Switching from permanent to temporary sewing in reverse has been optimized.
4.) The Start/Stop-button as well as the Start/Stop-function of the foot control has been precisely synchronized, i.e. the Start/Stop button shows a slightly dimmed stopping attitude.
5.) BSR-Zig-Zag Stitches: the function as for a stitch length shorter than 1.0mm has been optimized.
6.) Die icon of the oiling notification in the display disappears automatically after lubricating (after full elaboration of process)
7.) The personally set balance concerning the respective stitches has been improved for the user.
8.) The stitch patterns: 5, 7 and 1324 have been optimized

Kind regards

BERNINA International AG
Steckborn