BERNINA Firmware Release
BERNINA 580
V32.30.10

Steckborn, August 2012

The new firmware for BERNINA 580 has been optimized in following points:

Initial situation
Update of the Release-Firmware to version 32.30.10


1.) Saving the user data
   This function is new and available in the Setup menu.

We recommend the customer a periodic backup of the machine data on a PC via USB Stick – comparable to a backup of a PCs.

2.) New stitch plate: 5.5mm
The 5.5mm stitch plate 033 546.70.0X is integrated in the security menu.

3.) Support for DesignWorks
The machine supports the following modes of the DesignWorks family
- CutWork (cutting)
- PaintWork (painting)
- CrystalWork (punching)

4.) Zig-zag stitch functions with the Cutwork stitch plate are prevented

5.) Touch Screen calibration
The pixel misalignment while calibrating the screen has been optimized. Reason for optimizing: With older versions of the firmware the touch calibration could not have been performed optimally on each and every machine.

Information for Importers and dealers

BERNINA International AG keeps working on improvements and optimizations of their products due to customer feedback and the general technical development.

Kind regards

BERNINA International AG
Steckborn