Installation manual EConPC Update

Note:

The instructions take you step-by-step through the installation of EConPC Rel3.1 on a computer with a Windows® XP / Windows Vista™ or Windows® 7 operating system.
These instructions are also valid for further EConPC program updates – hence, the file names and illustrations used may be different, depending on the update and the installed operating system.In this installation manual, illustrations from Windows Vista™ are used.

Installation Requirements

- An operating BERNINA embroidery software ARTDesign V1.0G [1] installed on your Computer.
- All programs are closed.
- Administrator rights for your computer.
- Safety warnings during installation are confirmed with "**Execute**" or "**Continue**".

Step 1:

To start the download process, click on the link:

Step 2:

A dialog window will open:
Click on "**Save**"

Step 3:

A "**Save as ....**" window will open.
Select a path on your local PC
(**example: C:/Temp**).

Click on "**Save**" to download the ZIP file onto your computer.

---

[1] With BERNINA Embroidery Software ARTDesign V1's installed Service Pack 1.

Unselect "**Close this dialog box when download completes**" and click on "**Open**".

Step 4:

When the security message is displayed, click on "**Allow**".

Step 5:

To start the installation, click on the file:
**EConPC_Rel31_ARTDesign .exe.**

Step 6:

Depending on the setting and version of your Windows® operating system, a security message is displayed. To continue with the installation, click on the "**Continue**" or "**Execute**" button.

Step 7:

Select "**Next >**" to carry on with the installation. Follow the instructions on your screen.

Step 8:

Click on "**Finish**" to complete the installation of EConPC Rel31.

Step 9:

Close all open program windows and start up your BERNINA Embroidery Software ARTDesign V1. Open an embroidery motif and send it to the connected, switched-on aurora sewing machine, so that EConPC V3.1 starts up.