BERNINA^{TI}

Manuale d'installazione del aurora driver (64-bit)

Nota:

Every computer may be assembled and configured differently, which may mean differences from the messages and figures shown here. The different configurations may affect the behaviour.

Importante

Chiudere tutti i programmi, prima di avviare l'installazione. La macchina per cucire Aurora deve essere collegata tramite cavo USB con il PC. La macchina deve essere accesa. Confermare eventuali avvertenze di sicurezza con "Allow/OK".

1. Download

a. Cliccare sul link: Driver (64-Bit) for the aurora sewing machine (993KB)

b. Una finestra si apre, cliccare "Run/ OK"



c. Se il seguente messaggio può apparire, confermare con "Run/OK"



d. After that, the process for unpacking of the data, will start



e. Click on "Unzip", without changing the path



- f. The files will be unpacked in the following path: "C:\BERNINA_Downloads\aurora\Aurora_driver_64bit"
- **g.** The following message will be shown after successfully unzip of the files, click on "**OK**" to confirm:

25 file(s) unzipped succe	essfully

h. Choidere la finestra con "Close/ Chiudi"



BERNINA^{TI}

2. Installazione del driver per aurora

a. Cliccare "Start - Pannello di controllo - Sistema - Gestione periferiche ".

b. Mouse clic destro su "Aurora 430/440" con il punto esclamativo giallo e selezionare "Update Driver Software/ Aggiorna driver software "



c. Selezionare nella finestra seguente : "Browse my Computer for driver Software / Sfoglia per cercare il software del driver "



BERNINA^{TI}

d. Cliccare su "Browse", selezionare il seguente percorso:
"C:\BERNINA_downloads\aurora\Aurora_driver_64bit" e cliccare su "OK"

Browse for driver software on you	ur computer	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~
	Browse For Folder	25
Search for driver software in this location:	Select the folder that contains drivers for your	hardware.
C:\BERNINA_Downloads\aurora		
☑ Include subfolders	Windows Vista (C:) BERNINA BERNINA_Downloads	* 111
Let me pick from a list of de This list will show installed driver soft software in the same category as the	Aurora Aurora_driver_64Bit amd64 i386 RES_V5	•
· · · · · · · · · · · · · · · · · · ·	To view subfolders, dick the symbol next to a f	older.

e. Cliccare "Next" per avviare l'installazione:

	G 🛽 Update Driver Softwa	are - BERNINA aurora 430/440
	Browse for driver so	ftware on your computer
	Search for driver software in	n this location:
	C:\BERNINA_Downloads\a	surora\Aurora_driver_64Bit Browse
🕞 🗓 Update Driver Software - BERNINA aurora 430/440	Let me pick from This list will show ins software in the same	n a list of device drivers on my computer talled driver software compatible with the device, and all driver category as the device.
Installing driver software		Next Cancel
		Installazione in corso



f. Al termine dell'installazione riuscita appare il seguente messaggio, conferma con "**close/chiudi**"



g. Il driver per aurora è adesso installato.

3. Installazione del driver per la porta USB

- a. Aprire "Gestione periferiche" cliccando su "Start Pannello di controllo Sistema Gestioni periferiche ".
- **b.** Mouse clic destro su **"USB Serial Port"** con il punto esclamativo giallo e seleziona "Update **Driver Software**/Aggiorna...."



BERNINA[®]

c. Seleziona nella seguente finestra : "Browse my Computer for driver Software"



d. Cliccare su "Browse", e selezionare il seguente percorso:
"C:\BERNINA_downloads\aurora\Aurora_driver_64bit" e cliccare su "OK"

Browse for driver software on	your computer
	Browse For Folder
Search for driver software in this location	Select the folder that contains drivers for your hardware.
C:\BERNINA_Downloads\aurora\Auror	
Include subfolders	🖌 🚰 Windows Vista (C:)
	Dernina
	BERNINA_Downloads
	4 🤐 aurora
	Aurora_driver_64Bit
Let me pick from a list of a	i386
This list will show installed driver s	BES V5
software in the same category as t	
	To view subfolders, click the symbol next to a folder.
software in the same category as t	To view subfolders, click the symbol next to a folder.



e. Cliccare su "Next" per avviare l'installazione:



f. Al termine dell'installazione riuscita appare il messagio seguente, confermare con "**close**/chiudi"



g. Adesso il he driver dei USB Serial Port e installato.



4. Controllare i driver installati

a. Aprire "Gestioni periferiche" cliccando su "Start – Pannello di controllo – Sistema - Gestioni periferiche"

😤 Device Manager
File Action View Help
Portable Devices
Ports (COM & LPT)
BERNINA aurora 430/440 (COM5)
Communications Port (COIVII)
ECP Printer Port (LPT1)
Intel(R) Active Management Technology - SOL (COM3)
Processors
E Security Devices
Sound, video and game controllers
Storage controllers
Liniversal Serial Bus controllers
BERNINA aurora 430/440
Intel(R) ICH8 Family USB Universal Host Controller - 2830
Intel(R) ICH8 Family USB Universal Host Controller - 2831
Intel(R) ICH8 Family USB Universal Host Controller - 2834
🖬 🖣 Intel(R) ICH8 Family USB Universal Host Controller - 2835
Intel(R) ICH8 Family USB2 Enhanced Host Controller - 2836
Intel(R) ICH8 Family USB2 Enhanced Host Controller - 283A
USB Mass Storage Device
USB Root Hub

- **b.** Controllare in "Gestioni periferiche ", sotto "Porte (Com & LPT)" e "Universal Serial Bus controllers" le entrate (marcate di rosso) elencate.
- c. Chiudere tutte le finestra aperte
- d. Connettere il dongle del software BERNINA ad una porta USB libera ed avviare il software per ricamo BERNINA V5
- e. Aprire un ricamo e trasmetterlo nella macchina per cucire (il modulo per ricamo deve essere collegato.