

**BERNINA Firmware Release**  
**Q 20 / Q 24**  
**V 36.49.12**

Steckborn, 14.12.2016

**Information on Firmware Update**

The firmware for the BERNINA Q 20 and Q 24 has been updated and optimized. In this release note only the most relevant changes are listed.

**Note:**

BERNINA recommends all their customers of the corresponding product class to always use the latest software (Firmware release) as we keep on improving it according to customer feedback and wishes, considering new features, general optimization as well as a removal of defects to ensure the best possible sewing and embroidering experience on the BERNINA Product.

**Following improvements and adjustments have been made:**

- **New: „KickStart Functionality“ for Q 20 table versions**  
The KickStart function allows quilting in a continuous sewing mode without having to keep the foot control constantly pressed. The currently programmed functions of the foot control pedal are temporarily overwritten.
- **Optimization of BSR start behaviour**  
The response of the BSR (BERNINA Stitch Regulator) at the start was optimized.
- **Further error corrections and optimizations.**

BERNINA International AG endeavors to keep improving and optimizing their products basing on customer feedback and the latest technical developments.

Kind regards,

BERNINA International AG  
Steckborn, Switzerland