


Steckborn, 23. January 2018

Please note: compatibility firmware update B 770

In order to install firmware version V37.46.33 and higher, a flash capacity of at least 200'000 KB is required. Please check prior to the installation the size of the flash memory by entering the „Set Up“ menu and following the following path:



If the flash capacity is less than 200'000 KB you will not be able to successfully complete the installation process.

Please do not start the update process in this case, but use the firmware version V35.17.29 instead.

For more details please do not hesitate to contact your local BERNINA dealer.