

BERNINA Software/Firmware Release
Q-matic
V 2.01.53

Steckborn, April 2018

Information on Software/Firmware Update

The software for the BERNINA Q-matic has been updated and optimized.
In this release note only the most relevant changes are listed.

Note:

BERNINA recommends all their customers of the corresponding product to always use the latest software (firmware release) as we keep on improving according to customer feedback and wishes considering new features, general optimization as well as a removal of defects to ensure the best possible sewing experience with the BERNINA Product.

This software update installer (Q-matic-PC-Setup_2.01.53) includes the following parts:

Q-matic application V 2.01.53

Q-matic controller firmware qcs4239r108

Q series firmware V 37.47.42 (details according to separate release notes)

Following improvements and adjustments have been made:

- Screen flicker after Windows Update resolved
- Micro stitches after "pause" resolved
Bug causing micro stitches after "pause" in combination with un-ticked automatic "tie on" resolved.
- Default setting for sewing is now "ON".
- New pop-up when starting stitch out:
"Start at START point" and "Start at closest point on design"
- Further error corrections and optimizations

BERNINA International AG endeavors to keep improving and optimizing their products based on customer feedback and the latest technical developments.

Kind regards,

BERNINA International AG
Steckborn, Switzerland