

BERNINA Firmware Release
BERNINA Q series
V34.51.45

Steckborn, July 2015

Information on firmware

- 1.) Seven new languages were integrated: Danish, Spanish, Italian, Japanese, Dutch, Norwegian and Swedish.

Bugfix:

- 2.) Due to mechanical tolerances between the machine and the presser foot height sensor, in some cases the presser foot height sensor detects an overlift position by mistake. This results in the following error message:

Error Trigger_PresserFootIsUP

This circumstance has been eliminated with a logic control mechanism.

Fixes in previous versions
April 2015

Working with pantograph

When using the start/stop function on the rear right hand handle button (I) the machine start up delayed by approx. 1 second.

This has been changed to an instant start up.

Kind regards
BERNINA International AG
Steckborn