

BERNINA Firmware Release
BERNINA 530 and BERNINA 550 QE
V.20120319

Steckborn, 15th March 2012

The following issues of the latest Firmware concerning BERNINA 530 and BERNINA 550 have been optimized:

- 1.) As the minimum speed range was adjusted too hard, precise sewing with slightly pressed foot control was difficult. The sensitivity of the foot control has therefore been revised and optimized.
- 2.) The piercing support for thick and heavy material has been revised and optimized.
- 3.) Switching from permanent to temporary sewing in reverse has been optimized.
- 4.) The Start/Stop-button as well as the Start/Stop-function of the foot control has been precisely synchronized, i.e. the Start/Stop button shows a slightly dimmed stopping attitude.
- 5.) BSR-Zig-Zag Stitches: the function as for a stitch length shorter than 1.0mm has been optimized.
- 6.) Die icon of the oiling notification in the display disappears automatically after lubricating (after full elaboration of process)
- 7.) The personally set balance concerning the respective stitches has been improved for the user.
- 8.) The stitch patterns: 5, 7 and 1324 have been optimized

Kind regards

BERNINA International AG
Steckborn